

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	006	016	0000001543	See list below	Power Entry Module with Filter	5120

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
5120.0000.0	5120.0007.0	5120.0206.0	5120.0304.0	5120.0501.0
5120.0001.0	5120.0010.0	5120.0207.0	5120.0304.0.21	5120.0503.0
5120.0003.0	5120.0200.0	5120.0216.0	5120.0306.0	5120.0504.0
5120.0004.0	5120.0201.0	5120.0300.0	5120.0306.0.21	5120.0506.0
5120.0004.0.21	5120.0203.0	5120.0301.0	5120.0307.0	5120.0507.0
5120.0006.0	5120.0204.0	5120.0303.0	5120.0500.0	
5120.1000.0	5120.1006.0	5120.1203.0	5120.1301.0	5120.1307.0
5120.1000.0.21	5120.1006.0.21	5120.1204.0	5120.1303.0	5120.1503.0
5120.1001.0	5120.1007.0	5120.1206.0	5120.1304.0	5120.1504.0
5120.1003.0	5120.1200.0	5120.1207.0	5120.1306.0	5120.1506.0
5120.1004.0	5120.1201.0	5120.1300.0	5120.1306.0.21	5120.1507.0
5120.4000.0	5120.4070.0	5120.4077.0	5120.5073.0	5120.5374.0
5120.4001.0	5120.4071.0	5120.4373.0	5120.5074.0	
5120.4003.0	5120.4073.0	5120.4374.0	5120.5076.0	
5120.4004.0	5120.4074.0	5120.5070.0	5120.5077.0	
5120.4006.0	5120.4076.0	5120.5071.0	5120.5373.0	


2 Type of change

Filter cases for front and rear mounting have a new surface treatment process.

3 Detailed description of change


Surface treatment process of filter case has changed with no change of surface material.

Screw versions front-side



5120					0118.2246	
creation date	created by	release date	released by	notification no.	revision	page
2014-10-23	buechlp	2015-04-13	buechlp	26907	-	1 of 2

Screw versions rear-mounting



4 Reason of change

Improved production process.

5 Release date

The change will be rolled-out starting ww 04/2015 and lasts approx. 12 months depending on the variant.

6 Impact of change and recommended action

Form:	No	No change to form but more shiny surface
Fit:	No	There are no dimensional changes
Function:	No	This is a non-functional change
Production Site:	No	There is no change of the production site
Product Label:	No	No change to product label
Customer action	No	Notification only

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
List of affected part numbers	-	5120_PCN_affected part numbers.xlsx
Data sheet	5120	http://www.schurter.com/pdf/english/typ_5120.pdf

5120					0118.2246	
creation date	created by	release date	released by	notification no.	revision	page
2014-10-23	buech/pi	2015-04-13	buech/pi	26907	-	2 of 2