




Power Entry Module 5150 Screw version

Schurter part numbers 5150.XXXX.X

Package family	5150 SR					
Date	See below					
Version	See below					
						
Composition part	Material group	Materials	CAS if applicable	Average mass [weight-%] *	Sum [%]	Traces
Socket Insulation cover Cover filter case		PA66			10	
Metallparts		Copper	Cu		13	57
		Iron	Fe		38.8	
		Manganese	Mn		0.20	
		Nickel	Ni		0.10	
		Tin	Sn		0.9	
		Zinc	Zn		4.0	
Capacitor X2Y		Ceramic			11	33
		Potting			22	
Sum in total:					100	

Weight range	N/a	48,9 g
Fluctuation margin	N/a	

Part complies with RoHS 2002/95/EC (yes/no):	Yes	
Part complies with China RoHS (yes/no):	Yes	

or: Case sizes**) and weight range

N/a

*) related to package weight; weight in particular, see corresponding *package weight list*

**) optional

Not part of package family	N/a	
Company	SCHURTER AG	Important remarks: 1) Traces are product parts, substances etc. that are below a percentage of 0.1 % by weight. Higher limits are accepted if the substance or material is legally regulated (see note no. 2). 2) A list of the (legal) "... restrictions on substances ..." or materials is available at internet address: http://www.eicta.org/content/Default.asp?PageID=211 3) Substances, materials etc. with possible harmful effects on human beings and the environment are listed. 4) There are no risks for human beings and to the environment if products are properly used as designated. This shall not apply to risks caused during procedures for disposal etc. 5) All statements herein are based on our present knowledge. If our products are used properly, there are no risks to human beings and/or the environment.
Address	Werkhofstrasse 8-12 CH-6002 Luzern, Switzerland	
E-mail	contact@schurter.ch	
Internet	www.schurter.com	
Certified Management Systems	ISO 9001 since 1990 ISO 14001 since 1996 SA 8000 since 2004	

5150 Inlet filter					0104.0406	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
23.04.2008 15:09:58	HOA	23.04.2008	HOA	19664	-	1 von 1